



Cable Chart
Admin

The cable chart describes the connections for each lab device in the pod. Connections between control devices are not depicted (please refer to the Administrator Guide for guidance).

CABLE CHART FOR POD 3			
R1 (Cisco 1721)			
CONNECT FROM	USING CABLE	CONNECT TO	
FastEthernet0	CAT-5 Straight Through	C/S 2	Port 1
Console	Console Cable	A/S 1	Port 8
Power	Power Cord	SOD 1	Outlet 1
Serial0 DCE	Back-to-back serial cables	R2	Serial0 DTE
Serial1 DTE	Back-to-back serial cables	R3	Serial0 DCE
R2 (Cisco 1721)			
CONNECT FROM	USING CABLE	CONNECT TO	
FastEthernet0	CAT-5 Straight Through	C/S 2	Port 2
Console	Console Cable	A/S 1	Port 9
Power	Power Cord	SOD 1	Outlet 2
Serial0 DTE	Back-to-back serial cables	R1	Serial0 DCE
Serial1 DCE	Back-to-back serial cables	R3	Serial1 DTE
R3 (Cisco 1721)			
CONNECT FROM	USING CABLE	CONNECT TO	
FastEthernet0	CAT-5 Straight Through	C/S 2	Port 3
Console	Console Cable	A/S 1	Port 10
Power	Power Cord	SOD 1	Outlet 3
Serial0 DCE		R1	Serial1 DTE
Serial1 DTE	Back-to-back serial cables	R2	Serial1 DCE

Back